ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	4	Yelahanka Satellite Town
Street ID	**Street Name**	**Significant Landmark**
W0429	NA	GKVK layout
Segment No.	**Total Length (m)**	
4/S-W0429/S034727	113.57	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	113.57	77.588095	13.083685	77.588291	13.084694	W0384	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of Size stone masonry drain and covering slab on GKVK layout FROM GKVK Park to Hanumappa layout in ward no 04 Yelahanka new Satellite Tow	3000000	2014
Year	**Type of Work**	**Other Work Type**
2014 - 2015	Others	stone masonry drain and covering slab
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	Construction of Size stone masonry drain and covering slab on GKVK layout FROM GKVK Park to Hanumappa layout in ward no 04 Yelahanka new Satellite Town Sub-Division Yelahanka zone	004-15-000063
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE (YNK.D)/WO/111/2014-15	20/02/2015	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/09/2015	29/09/2016	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	

9449863065

Field Inspection Details

Number of Trees

0

Any Other Information

Name

DAYANANDA

Date of Inspection

08/04/2017

Remarks

COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	08/04/2017	08/05/2017	COMPLETED
SE	VASU K M	08/04/2017	08/05/2017	COMPLETED
EE	VASU K M	08/04/2017	08/05/2017	COMPLETED
AEE	JAGADISH	08/04/2017	08/05/2017	COMPLETED
AE	DAYANANDA	08/04/2017	08/05/2017	COMPLETED
AE	DAYANANDA	08/04/2017	08/05/2017	COMPLETED